

This Page Is Inserted by IFW Operations  
and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

## **IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning documents *will not* correct images,  
please do not report the images to the  
Image Problem Mailbox.**

AMN

TITLE: CLAMP IDENTIFICATION MARKER  
INVENTOR: RON WORTLEY  
DOCKET NO: 11984.5




FIG. 1




FIG. 2

TITLE: CLAMP IDENTIFICATION MARKER  
INVENTOR: RON WORTLEY  
DOCKET NO: 11984.5




Fig. 3

TITLE: CLAMP IDENTIFICATION MARKER  
INVENTOR: RON WORTLEY  
DOCKET NO: 11984.5




Fig. 5




Fig. 4

TITLE: CLAMP IDENTIFICATION MARKER  
INVENTOR: RON WORTLEY  
DOCKET NO: 11984.5




FIG. 7

PRIOR ART




FIG. 6

PRIOR ART




FIG. 8

TITLE: CLAMP IDENTIFICATION MARKER  
INVENTOR: RON WORTLEY  
DOCKET NO: 11984.5





FIG. 9

TITLE: CLAMP IDENTIFICATION MARKER  
INVENTOR: RON WORTLEY  
DOCKET NO: 11984.5



F16.10






FIG. 11